

Message

From: Shewmake, Kenneth [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=5031C1ABFE8847809A448EF4899DE65C-SHEWMAKE, KENNETH]
Sent: 1/28/2019 5:08:57 PM
To: Molly Beyer [Ex. 6 Personal Privacy (PP)] Rebecca Storms [Rebecca.Storms@tceq.texas.gov]
CC: jessica.kessinger@dshs.texas.gov; Pereira, Stephen [pereira.stephen@epa.gov]; Mekeel, Edward [mekeel.edward@epa.gov]; Rose.Walker@dshs.texas.gov; Richard Guldi [RLGuldi77@gmail.com]; Corey Troiani [corey@texasenvironment.org]
Subject: RE: RE: Lane Plating Superfund Site COC Report? (resend due to file size)

Molly,

I am the EPA remedial project manager (RPM) for Lane Plating. I just got back in the office after the 5 week shutdown. We have a draft sampling plan that we were reviewing before the shutdown started. We will probably need another month to review and revise this document due to the shutdown. I have not determined how much the schedule will need to be revised due to the shutdown.

We are planning to do sampling in phases. This means we will do additional sampling, if needed, after we review the results from phase one sampling. Our intention is to determine the extent of contamination originating from the Lane Plating site. If the data from the phase one sampling shows contamination is moving off the site then we will do additional sampling. Let me know if you have additional questions.

Kenneth Shewmake
US Environmental Protection Agency
Environmental Scientist
RPM Lane Plating Superfund Site

1445 Ross Ave., Suite 1200
Dallas, TX 75202-2733
shewmake.kenneth@epa.gov
work phone- (214) 665-3198

From: Molly Beyer [Ex. 6 Personal Privacy (PP)]
Sent: Wednesday, January 16, 2019 3:46 PM
To: Rebecca Storms <Rebecca.Storms@tceq.texas.gov>
Cc: jessica.kessinger@dshs.texas.gov; Shewmake, Kenneth <shewmake.kenneth@epa.gov>; Pereira, Stephen <pereira.stephen@epa.gov>; Mekeel, Edward <mekeel.edward@epa.gov>; Rose.Walker@dshs.texas.gov; Richard Guldi [Ex. 6 Personal Privacy (PP)] Corey Troiani <corey@texasenvironment.org>
Subject: Re: RE: Lane Plating Superfund Site COC Report? (resend due to file size)

Thanks for the update, Rebecca!

On Wed, Jan 16, 2019 at 3:40 PM Rebecca Storms <Rebecca.Storms@tceq.texas.gov> wrote:

Hello Molly,

The EPA is the lead agency for this site. I understand that EPA is still working on the plans for the next steps at the site. As soon as EPA is back in the office, we will know more and I will ask that they follow up with you.

Thank you,

Rebecca Storms, P.G.

Superfund Section, MC-136

Remediation Division

Texas Commission on Environmental Quality

Phone: 512-239-2466

Email: Rebecca.Storms@tceq.texas.gov



From: Molly Beyer <[Ex. 6 Personal Privacy \(PP\)](#)>

Sent: Monday, January 14, 2019 10:08 AM

To: Rebecca Storms <Rebecca.Storms@Tceq.Texas.Gov>; jessica.kessinger@dshs.texas.gov;
shewmake.kenneth@epa.gov; pereira.stephen@epa.gov; mekeel.edward@epa.gov; Rose.Walker@dshs.texas.gov

Cc: Richard Guldi <[Ex. 6 Personal Privacy \(PP\)](#)>; Corey Troiani <corey@texasenvironment.org>

Subject: Re: RE: Lane Plating Superfund Site COC Report? (resend due to file size)

Hi all,

I hope things are going okay amid the government shutdown.

I am emailing because I am wondering if you all could give me information about the planned upcoming additional testing surrounding the site (surface water flow, soil samples, sediment, etc), particularly to the Southeast of the site. How far out is planning on being tested and what is the logic with this decision? Any assets you could share detailing testing plans and expected date of processing and release of that information would be very helpful.

Thanks for your time,

Molly Beyer

On Mon, Nov 19, 2018 at 9:12 AM Rebecca Storms <Rebecca.Storms@tceq.texas.gov> wrote:

Hello Molly,

I've attached the last lab report of data collected by TCEQ during the SI:

- ALS MF1D00, MF1D18, and MF1D37: SI cyanide results.

Thanks and have a good Thanksgiving,

Rebecca

From: Rebecca Storms

Sent: Monday, November 19, 2018 9:06 AM

To: 'Molly Beyer' <[Ex. 6 Personal Privacy \(PP\)](#)>

Cc: <[Ex. 6 Personal Privacy \(PP\)](#)> 'jessica.kessinger@dshs.texas.gov' <jessica.kessinger@dshs.texas.gov>; 'mekeel.edward@epa.gov' <mekeel.edward@epa.gov>; 'shewmake.kenneth@epa.gov' <shewmake.kenneth@epa.gov>; 'pereira.stephen@epa.gov' <pereira.stephen@epa.gov>; 'Rose.Walker@dshs.texas.gov' <Rose.Walker@dshs.texas.gov>

Subject: RE: Lane Plating Superfund Site COC Report? (resend due to file size)

Hello Molly,

I am sending you the laboratory results for the Site Investigation (SI) sampling that was performed by TCEQ (soil, sediment, and surface water results), in addition to on-site groundwater data that was collected by TCEQ's region office. The SI data was the main basis of the Hazard Ranking Score and National Priorities List ranking for the site. I'm attaching the following lab reports:

- XENCO 525767: Grab samples collected from the two on-site water wells. Sample 1: west well; Sample 2: duplicate of Sample 1; Sample 3: North well.
- EPA R6 16SF093: SI metals and mercury results.
- EPA R6: SI Data Review

- TCEQ: SI Audit Data Quality

Due to file size, I will send you the remaining lab report in a separate email.

The EPA collected additional soil samples around the facility building. I would contact the EPA for these soil results.

Please let me know if you have any questions about this data.

Thank you,

Rebecca Storms, P.G.

Superfund Section, MC-136

Remediation Division

Texas Commission on Environmental Quality

Phone: 512-239-2466

Email: Rebecca.Storms@tceq.texas.gov



--

Regards,

Molly Beyer

Ex. 6 Personal Privacy (PP)

--

Regards,

Molly Beyer

Ex. 6 Personal Privacy (PP)